

Supplemental Type Certificate

Number ST01585LA

This Certificate issued to

Global AirWorks
19933 Harrison Ave.
City of Industry, California 91789

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet.*

Original Product Type Certificate Number: A46NM

Make: Airbus

Model: A330-201, -202, -303, -223, -243, -301, -321, -322, -323, -341, -342, and -343

Description of Type Design Change: Installation of AirWorks Cockpit Door Surveillance Systems in accordance with FAA Approved AirWorks Index List Document No. IL23009, Revision A, dated January 30, 2004, or later FAA approved revision. AirWorks Airplane Flight Manual Supplement Document No. AFMS230019, Revision Original, FAA approved on February 26, 2004, or later FAA approved revision, is required as part of this modification.

Limitations and Conditions This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 22, 2003

Date reissued: July 29, 2004; Oct. 24, 2006,
September 22, 2009, March 1, 2010

Date of issuance: February 27, 2004

Date amended: May 24, 2005



By direction of the Administrator

(Signature)

Manger, Systems and Equipment Branch,
Los Angeles Aircraft Certification Office

alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.